

Lee County Board of Education  
2410 Society Hill Road  
Opelika, AL 36804-4830



Dr. James E. McCoy  
Superintendent  
334-705-6000  
Fax: 334-745-9774

---

*A Tradition of Excellence-A Vision for Tomorrow*

---

December 17, 2018

To Whom It May Concern:

All Lee County Schools have been inspected by an EPA approved asbestos inspector. The majority of our asbestos material is non-friable and is in the form of floor tiles. These materials are well maintained and are not a health hazard to the students.


A management plan file is prepared and maintained as required under the AHERA regulations. The law requires that we make this notice available to all employees, students, and staff annually.

Due to this process we are able to provide a healthy atmosphere for students and staff.

Sincerely,

A handwritten signature in black ink, appearing to read "Marcus Fuller".

Marcus Fuller  
Assistant Superintendent  
Operations



RainCrow

Environmental

***Triennial Asbestos  
Re-inspection  
Report***

**Lee County BOE  
2410 Society Hill Rd.  
Opelika, AL 36804**

**November 15<sup>th</sup>, 2018**

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

**LEA: Lee County BOE**  
**Beauregard High School**  
**7343 AL Highway 51**  
**Opelika, Alabama 36804**

**REINSPECTION DATE:** 11/15/18

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL0518257655

**SIGNATURE:** Stan Eller


**COMMENTS AND INSTRUCTIONS:**

Since the last inspection, several buildings have either been demolished or gutted in preparation for total renovation.

All changes in material are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- Any and all renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program  
AHERA Reinspection Form**


Date of Previous Inspection – 11-12-15					Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education					LEA # 041									
School Name – Beauregard High School					School # 010									
Building Name - High School Building (1978 Wing)					Building # 01									
Address: 7343 AL Highway 51 Opelika, Alabama 36804					Inspector's Name – Stan Eller									
					Signature - 									
<b>This building has been demolished.</b>					Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 transite ceiling tiles (Side Porches) 80 sf		5- sinks(@ old Home Ec CR )Black Spray on															
			No.	11-01	55-01															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing				X															
	Miscellaneous			X																
	Assumed ACBM		X		X															
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable		X		X															
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			Y		Y															
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				




**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Beauregard High School										School # 010									
Building Name - Lunch Room Building (Old)										Building # 02									
Address: 7343 AL Highway 51 Opelika, Alabama 36804										Inspector's Name – Stan Eller									
										Signature - 									
<b>This building has been demolished.</b>										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2- Sinks W/ Black Spray-on		1 – Fire-door															
			No.	55-01	51-01															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing		X																	
	Miscellaneous				X															
	Assumed ACBM		X		X															
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable		X		X															
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			Y		Y															
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Beauregard High School										School # 010									
Building Name - Gym										Building # 03									
Address: 7343 AL Highway 51 Opelika, Alabama 36804										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Vinyl Floor Tile (Lobby) white – 1,800 sf	Vinyl Floor Tile (Foyer) brown – 240 sf	4- "Modine" Gas Ceiling Heaters (Court Area)															
			No.	30-01	30-02	51-01														
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI						X													
	Surfacing																			
	Miscellaneous		X		X															
	Assumed ACBM						X	X												
	Sampled/Tested		X		X															
	Non ACBM																			
	ACBM		X		X															
	Nonfriable		X		X		X	X												
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N													
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category			Replaced W / New 12" Vinyl Floor Tile.		Replaced W / New 12" Vinyl Floor Tile.		Not Listed Originally													


**Alabama Asbestos Management Program  
AHRA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Beauregard High School										School # 010									
Building Name - Vocational Building										Building # 04									
Address: 7343 AL Highway 51 Opelika, Alabama 36804										Inspector's Name – Stan Eller									
										Signature - 									
<b>This building has been renovated.</b>										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl Floor Tile (Classroom) white – 1,200 sf		12" Vinyl Floor Tile (Classroom Side Area) white – 560 sf		2 – Sinks W/ Black Spray-on		1- Modine Gas Ceiling Heater (Shop Area)		1- Janitron Gas Ceiling Heater (Shop Area)											
			No.																			
			30-01		30-02		51-01		52-01		53-01											
			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI								X		X											
	Surfacing					X																
	Miscellaneous	X		X																		
	Assumed ACBM					X	X	X		X												
	Sampled/Tested	X		X																		
	Non ACBM																					
	ACBM	X		X																		
	Nonfriable	X		X		X	X	X		X												
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)		N		N		N		Y		Y												
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
	40 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category		Replaced W / New 12" Vinyl Floor Tile.		Replaced W / New 12" Vinyl Floor Tile.				Removed		Removed												


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Beauregard High School										School # 010									
Building Name - 1978 Band Room										Building # 05									
Address: 7343 AL Highway 51 Opelika, Alabama 36804										Inspector's Name – Stan Eller									
<b>This building has been renovated.</b>										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	4- Firedoors		1- Sink W/ Black Spray-on (Office Work Room)															
			No.	51-01	55-01															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing				X															
	Miscellaneous			X																
	Assumed ACBM		X		X															
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable		X		X															
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			Y		Y															
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Beauregard High School										School # 010									
Building Name - Shop Building										Building # 06									
Address: 7343 AL Highway 51 Opelika, Alabama 36804										Inspector's Name – Stan Eller									
										Signature - 									
This building has been renovated.										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl Floor Tile (Classroom) - 1,100 sf	No.	30-01	Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now	
Inspection/Reinspection					Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																																
	Surfacing																																
	Miscellaneous				X																												
	Assumed ACBM																																
	Sampled/Tested				X																												
	Non ACBM																																
	ACBM				X																												
	Nonfriable				X																												
Friable																																	
Assessment/Reassessment																																	
Change in Condition? (Y/N)					N																												
Rate 1 To 5 5 is Worst	Deterioration																																
	Physical Damage																																
	Water Damage																																
	Activity/Vibration																																
	Exposure																																
Length of Exposure	Accessibility																																
	1 Hour/Week																																
	5 Hours/Week																																
	10 Hours/Week																																
	20 Hours/Week																																
	40 Hours/Week																																
Check All That Apply	Maintenance																																
	Custodial																																
	Faculty/Students																																
	Public																																
Assessment Category																																	


[illegible]

Alabama Asbestos Management Program AHERA Reinspection Form																				
Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18										
LEA Name - Lee County Board of Education										LEA # 041										
School Name – Beauregard High School										School # 010										
Building Name - 1981 Elementary Wing (Old 2 <sup>nd</sup> & 3 <sup>rd</sup> Grade)										Building # 08										
Address: 7343 AL Highway 51 Opelika, Alabama 36804										Inspector's Name – Stan Eller										
										Signature - 										
										Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	5- Firedoors (1981 Wing) Wood		4- sinks W/ White Spray-on (1981 Wing)		4 Fire-doors (1983 Wing) – Wood		4- Sinks W/ Mauve Spray on (1983 Wing)		2- Fire-doors (Hall)									
			No.	51-01	55-01	52-01	56-01	51-02												
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing				X				X											
	Miscellaneous			X			X				X									
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X								
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable		X	X	X	X	X	X	X	X	X	X								
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N		N		N									
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
	Assessment Category		Not Listed Originally		Not Listed Originally		Not Listed Originally		Not Listed Originally		Not Listed Originally									



Alabama Asbestos Management Program AHERA Reinspection Form																				
Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18										
LEA Name - Lee County Board of Education										LEA # 041										
School Name – Beauregard High School										School # 010										
Building Name - Middle Grades Building										Building # 09										
Address: 7343 AL Highway 51 Opelika, Alabama 36804										Inspector's Name – Stan Eller										
										Signature - 										
This building has been demolished.										Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl Floor Tile (Corridor) red - 350 sf		12" Vinyl Floor Tile (Classrooms) -2,300 sf		12" VFT (Last CR @ End/Hall) Beige W/ Green Streaks-800 sf		9" Vinyl Floor Tile (Last CR Restroom @ End/Hall)											
			No.	30-01	30-02	31-01	32-01													
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X		X											
	Assumed ACBM						X		X											
	Sampled/Tested		X		X															
	Non ACBM																			
	ACBM		X		X															
	Nonfriable		X		X		X		X											
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		Y		Y											
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category			Replaced W / New 12" Vinyl Floor Tile.		Replaced W / New 12" Vinyl Floor Tile.		Not Listed Originally		Not Listed Originally. Could Be Under Classroom Tile.											



Alabama Asbestos Management Program AHERA Reinspection Form																				
Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18										
LEA Name - Lee County Board of Education										LEA # 041										
School Name – Beauregard High School										School # 010										
Building Name - 1972 Gym										Building # 010										
Address: 7343 AL Highway 51 Opelika, Alabama 36804										Inspector's Name – Stan Eller										
										Signature - 										
This building has been demolished.										Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2- Janitron Gas Ceiling Heaters		2- Reznor Gas Ceiling Heaters															
			No.	52-01	53-01															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X															
	Assumed ACBM		X		X															
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable		X		X															
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			Y		Y															
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
Faculty/Students																				
Public																				
Assessment Category																				

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

**LEA: Lee County BOE  
Beulah High School  
4848 Lee Road  
Valley, Alabama 36854**

**REINSPECTION DATE:** 11/15/18

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL0518257655


**SIGNATURE:** 


**COMMENTS AND INSTRUCTIONS:**


Since the last inspection, the *Elementary Building* (08) has been added to the management plan due to materials that were determined to be suspect ACBM.


All changes in material are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:


- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- Any and all renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

Alabama Asbestos Management Program AHERA Reinspection Form																						
Date of Previous Inspection – 11-10-15										Date Of Reinspection – 11-15-18												
LEA Name - Lee County Board of Education										LEA # 041												
School Name – Beulah High School										School # 020												
Building Name - Main School Building										Building # 01												
Address: 4848 Lee Road Valley, Alabama 36854										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Vinyl Floor Tile Hall & Classrooms 1 & 2) white -1,000 sf		Vinyl Floor Tile (Corridors) white-250 sf		Vinyl Floor Tile (Library Storage) brown -75 sf		Vinyl Floor Tile (Library Entry) yellow -25 sf		2- Firedoors (Custodial Closet)		1-Firedoor (Custodial Closet @ Restrooms)		Pipe Valve Insulation (Custodial Closet @ Restrooms)		Transite Window Panels (Office)		17- Black Stair Treads @ Library Entry		1- Sink W/ Black Spray on (Basement Lab CR)	
			No.	30-01	30-02	31-03	32-04	51-01	51-02	40-01	11-01	33-01	55-01									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM										X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested		X		X		X		X													
	Non ACBM																					
	ACBM		X		X		X	X	X	X												
	Nonfriable		X		X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable													X	X								
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category			Replaced W / New 12" Vinyl Floor Tile.		Replaced W / New 12" Vinyl Floor Tile.						Not Listed Originally		Not Listed Originally		Not Listed Originally		Not Listed Originally		Not Listed Originally		Not Listed Originally	

Alabama Asbestos Management Program AHERA Reinspection Form																				
Date of Previous Inspection – 11-10-15										Date Of Reinspection – 11-15-18										
LEA Name - Lee County Board of Education										LEA # 041										
School Name – Beulah High School										School # 020										
Building Name - Main School Building										Building # 01										
Address: 4848 Lee Road Valley, Alabama 36854										Inspector's Name – Stan Eller										
										Signature - 										
										Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	1- Lab Hood W/ Lining (Basement Lab)	Lab Counter tops (Basement Lab)	Gypsum Duct (Basement Library Storage)															
			No.	62-01	44-01	22-01														
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X													
	Assumed ACBM		X	X	X	X														
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable		X	X	X	X														
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		Y													
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
	Assessment Category																			

Alabama Asbestos Management Program AHERA Reinspection Form																					
Date of Previous Inspection – 11-10-15											Date Of Reinspection – 11-15-18										
LEA Name - Lee County Board of Education											LEA # 041										
School Name – Beulah High School											School # 020										
Building Name - Lunchroom											Building # 02										
Address: 4848 Lee Road Valley, Alabama 36854											Inspector's Name – Stan Eller										
											Signature - 										
											Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	3-Firedoors																		
				No.	41-01																
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																				
	Surfacing																				
	Miscellaneous		X																		
	Assumed ACBM		X	X																	
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable		X	X																	
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)			N																		
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
	40 Hours/Week																				
Check All That Apply	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category																					


Alabama Asbestos Management Program AHERA Reinspection Form																				
Date of Previous Inspection – 11-10-15										Date Of Reinspection – 11-15-18										
LEA Name - Lee County Board of Education										LEA # 041										
School Name – Beulah High School										School # 020										
Building Name - Home Economics										Building # 04										
Address: 4848 Lee Road Valley, Alabama 36854										Inspector's Name – Stan Eller										
										Signature - 										
										Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	5- Sinks W/ White Spray-on																	
				No.	55-01															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing		X																	
	Miscellaneous																			
	Assumed ACBM			X																
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable			X																
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			Y																	
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				

Alabama Asbestos Management Program AHERA Reinspection Form																				
Date of Previous Inspection – 11-10-15										Date Of Reinspection – 11-15-18										
LEA Name - Lee County Board of Education										LEA # 041										
School Name – Beulah High School										School # 020										
Building Name - Agribusiness Building										Building # 05										
Address: 4848 Lee Road Valley, Alabama 36854										Inspector's Name – Stan Eller										
										Signature - 										
										Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Vinyl Floor Tile (Classroom) white – 522 sf	Vinyl Floor Tile (Classroom) brown - 522 sf	Sheetrock Ceiling (Shop Entry) 200 sf @ Restrooms	1-Fire-door (Shop Area)														
			No.	30-01	31-02	22-01	51-01													
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X													
	Assumed ACBM						X	X		X										
	Sampled/Tested		X		X															
	Non ACBM																			
	ACBM		X	X	X	X														
	Nonfriable		X	X	X	X	X	X		X										
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N		Y											
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				

Not Listed Originally.



**Alabama Asbestos Management Program  
AHERA Reinspection Form**


Date of Previous Inspection – 11-10-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Beulah High School										School # 020									
Building Name - Gym Building										Building # 07									
Address: 4848 Lee Road Valley, Alabama 36854										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Vinyl Floor Tile - white 250 sf	2- 4" Pipe Fitting	5- Firedoors (Old Gym Hall Area)	12" VFT (Old Gym Hall) White W/ Grey Marbled -330 SF	4" Vinyl Cove Base Mastic (Old Gym Thru out)											
			No.	30-01	01-02	51-01	33-01	41-01										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI				X													
	Surfacing																	
	Miscellaneous		X			X	X	X	X	X								
	Assumed ACBM					X	X	X	X	X								
	Sampled/Tested		X		X													
	Non ACBM																	
	ACBM		X		X													
	Nonfriable		X		X	X	X	X	X	X								
Friable																		
Assessment/Reassessment																		
Change in Condition? (Y/N)			N		N		N		N		N							
Rate 1 To 5 5 is Worst	Deterioration																	
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
Check All That Apply	40 Hours/Week																	
	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
	Assessment Category		Removed		Removed		Not Listed Originally.		Not Listed Originally.		Not Listed Originally.							



**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – N/A										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Beulah High School										School # 020									
Building Name – Elementary Building										Building # 08									
Address: 4848 Lee Road Valley, Alabama 36854										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	8- Inter. window panels		2- Metal firedoors		14- Wood firedoors		8- Sinks w/ black spray-on									
			No.															
			01-01		02-01		03-01		04-01									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																	
	Surfacing								X									
	Miscellaneous		X		X		X											
	Assumed ACBM			X		X		X		X								
	Sampled/Tested																	
	Non ACBM																	
	ACBM																	
	Nonfriable			X		X		X		X								
Friable																		
Assessment/Reassessment																		
Change in Condition? (Y/N)			Y		Y		Y		Y									
Rate 1 To 5 5 is Worst	Deterioration																	
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
Check All That Apply	40 Hours/Week																	
	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
	Assessment Category																	

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

**LEA: Lee County BOE**  
**Loachapoka High School**  
**685 Lee Road 61**  
**Loachapoka, Alabama 36864**

**REINSPECTION DATE:** 11/15/18

**INSPECTOR:** Stan Eller


**ACCREDITATION NO.:** APL0518257655

**SIGNATURE:** 


**COMMENTS AND INSTRUCTIONS:**

All changes in material are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- Any and all renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

Alabama Asbestos Management Program AHERA Reinspection Form																				
Date of Previous Inspection – 11-12-15										Date Of Reinspection –11-15-18										
LEA Name - Lee County Board of Education										LEA # 041										
School Name – Loachapoka High School										School # 030										
Building Name - High School Building										Building # 02										
Address: 685 Lee Road 61 Loachapoka, Alabama 36865										Inspector's Name – Stan Eller										
										Signature - 										
										Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl Floor Tile (Corridor) brown – 2,100 sf		12" Vinyl Floor Tile (Corridors) brn w/ drk brwn flecks-1,700 sf		12" Vinyl Floor Tile (Classrooms) brn w/ drk brwn flecks- 12,000 sf		12" Vinyl Floor Tile (Classrooms) white – 3,600 sf		12" Vinyl Floor Tile (Library) white –1100 sf		12" Vinyl Floor Tile (Cafeteria) green – 2,500 sf		8- Firedoors (Hall)		1- Sink W Black Spray-on (Home Economics)		Lab Countertops (Science Lab)	
			No.	30-01	31-01	31-02	32-02	33-03	36-05	51-01	55-01	57-01								
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X		X		X		X		X		X		X	
	Assumed ACBM														X	X	X	X		X
	Sampled/Tested		X		X		X		X		X		X							
	Non ACBM																			
	ACBM		X		X		X	X	X	X	X		X							
	Nonfriable		X		X		X	X	X	X	X		X		X	X	X	X		X
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		Y		Y		N		N		N		N		Y	
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category			Replaced W / New 12" Vinyl Floor Tile.		Replaced W / New 12" Vinyl Floor Tile.		400 sf Removed From Former Lab. The Remainder is Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Renovated In 2003.		Removed		Not Listed Originally.		Not Listed Originally.		Not Listed Originally.	

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Loachapoka High School										School # 030									
Building Name - Gym Building										Building # 03									
Address: 685 Lee Road 61 Loachapoka, Alabama 36865										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Vinyl Floor Tile (Lobby) - white 850 sf		Vinyl Floor Tile (Coach's Lt. Side Office) - white		2- Modine Gas Heaters (Girls Locker Room)		2- Modine Gas Heaters (Boys Locker Room)		12" Vinyl Floor Tile (Concession Stand) -tan marbled- 150 sf								
			No.	30-01	30-03	52-01	52-02	31-04											
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI						X		X										
	Surfacing																		
	Miscellaneous		X		X						X								
	Assumed ACBM						X	X	X	X	X								
	Sampled/Tested		X		X														
	Non ACBM																		
	ACBM		X		X	X													
	Nonfriable		X		X	X	X	X	X	X	X								
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)			N		N		Y		Y		Y								
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
Public																			
Assessment Category			Replaced W / New 12" Vinyl Floor Tile.			Office Covered W/ Carpet (Floor Tile Determined to be Light Tan)			Not Listed Originally. One Replaced.			Not Listed Originally. One Replaced.			Not Listed Originally & All Removed During Renovations.				

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

**LEA: Lee County BOE  
Sanford Middle School  
1500 Lee Road 11  
Opelika, Alabama 36804**

**REINSPECTION DATE:** 11/15/18

**INSPECTOR:** Stan Eller


**ACCREDITATION NO.:** APL0518257655

**SIGNATURE:** 


**COMMENTS AND INSTRUCTIONS:**

All changes in material are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- Any and all renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

Alabama Asbestos Management Program AHERA Reinspection Form																				
Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18										
LEA Name - Lee County Board of Education										LEA # 041										
School Name – Sanford Middle School										School # 040										
Building Name - Middle School Building										Building # 01										
Address: 1500 Lee Road 11 Opelika, Alabama 36804										Inspector's Name – Stan Eller										
										Signature - 										
										Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl Floor Tile (Corridor) white -5,000 sf		12" Vinyl Floor Tile (Cafeteria) white -1,100 sf		12" Vinyl Floor Tile (Classrooms & Offices) brown -18,650 sf		12" Vinyl Floor Tile (Cafeteria) brown - 2,000 sf		12" VFT (12 classrooms) Light Green W/ Olive		12" VFT (5 Classrooms) Tan W/ Grey Streaks		12" VFT (Teacher's Lounge) Light Green W/ Grey Streaks		1- Fire-door		4- Fire-doors (Office Area)	
			No.	30-01	30-03	31-02	31-03	32-01	33-02	34-03	51-01	51-02								
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X		X		X		X		X		X		X	
	Assumed ACBM										X	X	X	X	X	X	X	X		
	Sampled/Tested		X		X		X		X											
	Non ACBM																			
	ACBM		X		X		X	X	X	X										
	Nonfriable		X		X		X	X	X	X	X	X	X	X	X	X	X		X	
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		Y	
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category			Replaced W / New 12" Vinyl Floor Tile.		Replaced W / New 12" Vinyl Floor Tile @ Café Now Library W/ Carpet		Replaced 1,000 SF W / New 12" Vinyl Floor Tile @ Offices Remainder Covered W/ Old 12" VFT		Replaced W / New 12" Vinyl Floor Tile @ Cafe		Not Listed Originally.		Not Listed Originally.		Not Listed Originally.		Not Listed Originally.		Not Listed Originally.	

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Sanford Middle School										School # 040									
Building Name - Gym Building										Building # 02									
Address: 1500 Lee Road 11 Opelika, Alabama 36804										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" Vinyl Floor Tile (Classroom 23 & Boys LR CR) brn -1,100 sf	9" Vinyl Floor Tile (Classrooms) white - 2,000sf	4 – Janitron Gas Ceiling Heater (Court Area)	1- Janitron Gas Ceiling Heater (Lobby area)														
			No.	30-01	31-01	52-01	52-02													
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI					X		X												
	Surfacing																			
	Miscellaneous		X		X															
	Assumed ACBM						X	X	X	X										
	Sampled/Tested		X		X															
	Non ACBM																			
	ACBM		X	X	X															
	Nonfriable		X	X	X		X	X	X	X										
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N		N											
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
Public																				
Assessment Category			Tan W/ Cream Streaks (Also Found @ Office Closet)			Replaced W / New Commercial Carpet.			Not Listed Originally.			Not Listed Originally.								



Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

**LEA: Lee County BOE  
Smiths Station Primary School  
150 Lee Road  
Smiths Station, Alabama 36877**

**REINSPECTION DATE:** 11/12/15

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL0515257655

**SIGNATURE:** Stan Eller


**COMMENTS AND INSTRUCTIONS:**

All changes in material are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- Any and all renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**



**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Smith Station Primary (Now West S.S. Elem.)										School # 050									
Building Name - First Grade										Building # 02									
Address: 150 Lee Rd. Smiths Station, Alabama 36877										Inspector's Name – Stan Eller									
										Signature - 									
Now: West Smiths Station Elementary										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" VFT (Cafeteria) white – 1,600 sf		9" VFT (Classrooms 1 & 2) tan marbled w/ brwn streaks – 1,500 sf		9" VFT (Classrooms 3 - 8 & Off.) dark maroon - 4,050 sf		9" VFT (Hall) dark tan w/ white streaks – 1300 sf									
			No.	30-01	31-02	32-03	33-04											
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																	
	Surfacing																	
	Miscellaneous		X		X		X		X									
	Assumed ACBM																	
	Sampled/Tested		X		X		X		X									
	Non ACBM																	
	ACBM		X		X		X		X									
	Nonfriable		X		X		X		X									
Friable																		
Assessment/Reassessment																		
Change in Condition? (Y/N)			N		N		N		N									
Rate 1 To 5 5 is Worst	Deterioration																	
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
	40 Hours/Week																	
Check All That Apply	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
Assessment Category			Replaced W/ New 12" Vinyl Floor Tile.		Covered or Replaced W/ New 12" Vinyl Floor Tile. Replaced According to 1992 Report.		Covered or Replaced W/ New 12" Vinyl Floor Tile. Replaced according To 1992 Report.		Replaced According To 1992 Report.									

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

**LEA: Lee County BOE**  
**Smiths Station High School (Now Jr. High)**  
**1100 Lee Road**  
**Smiths Station, Alabama 36877**

**REINSPECTION DATE:** 11/15/18

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL0518257655


**SIGNATURE:** Stan Eller

**COMMENTS AND INSTRUCTIONS:**

All changes in material are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- Any and all renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Smith Station High (Now Junior High)										School # 060									
Building Name - Admin. & Class (High)										Building # 01									
Address: 1100 Lee Rd. Smiths Station, Alabama 36877										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Drywall Joint Compound (Admin. Office) – 700 sf		1- Sink W/ White Spray-on Material (Admin. Kitchen)		1- Firedoor (Storage /Supply Room/ Storage @ Admin. Office)		1- Sink W/ White Spray-on (Library work Room)		Transite Panels(Library Windows)		Dry Wall ( old Café @ Vaulted Ceiling)									
			No.																			
			02-08		55-01		51-01		55-02		11-01		22-01									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing				X				X													
	Miscellaneous		X				X				X		X									
	Assumed ACBM				X	X	X	X	X	X	X	X	X	X								
	Sampled/Tested		X																			
	Non ACBM																					
	ACBM		X	X																		
	Nonfriable				X	X	X	X	X	X	X	X	X	X								
Friable		X	X																			
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N									
Rate 1 To 5 5 is Worst	Deterioration		1	1																		
	Physical Damage		1	1																		
	Water Damage		1	1																		
	Activity/Vibration		1	1																		
	Exposure		1	1																		
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
	40 Hours/Week		X	X																		
Check All That Apply	Maintenance		X	X																		
	Custodial		X	X																		
	Faculty/Students		X	X																		
	Public																					
Assessment Category			5	5	Not Listed Originally.		Not Listed Originally.		Not Listed Originally.		Not Listed Originally.		Not Listed Originally.									


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Smiths Station High (Now Junior High)										School # 060									
Building Name - Gym (Old High School)										Building # 02									
Address: 1100 Lee Rd. Smiths Station, Alabama 36877										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" VFT (Lobby) white – 1400 sf		4 – "Modine" Gas Ceiling Heaters / Linings (Court Area)															
			No.																	
			30-01		50-01															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI				X															
	Surfacing																			
	Miscellaneous			X																
	Assumed ACBM				X	X														
	Sampled/Tested		X																	
	Non ACBM																			
	ACBM		X																	
	Nonfriable		X		X	X														
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N															
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection –11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Smith Station High (Now Junior High)										School # 060									
Building Name - Science Wing (High)										Building # 03									
Address: 1100 Lee Rd. Smiths Station, Alabama 36877										Inspector's Name – Stan Eller									
(Now designated as Building #5.)										Signature - 									
Alabama Accreditation No. – APL0518257655																			


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	3- Sinks W/ Black Spray-on Material (Science Lab)		7-sinks W/ Black Spray-on (Classrooms)		14- Firedoors (Trough out)													
			No.	55-01	55-02	51-01														
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X													
	Assumed ACBM		X	X	X	X	X	X												
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable		X	X	X	X	X	X												
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N													
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category			Not Listed Originally.		Not Listed Originally.		Not Listed Originally.													





**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Smiths Station High (Now Junior High)										School # 060									
Building Name - Gym (Old Elementary)										Building # 07									
Address: 1100 Lee Rd. Smiths Station, Alabama 36877										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" VFT (Lobby) brown – 500 sf	12" VFT (Offices) brown – 1,000 sf															
			No.	30-01	31-02														
	Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.
Check one	TSI																		
	Surfacing																		
	Miscellaneous		X		X														
	Assumed ACBM																		
	Sampled/Tested		X		X														
	Non ACBM																		
	ACBM		X		X														
	Nonfriable		X		X														
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N															
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
	40 Hours/Week																		
Check All That Apply	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category																			

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, Al. 36022

Cell Phone: 334-315-2892

**LEA: Lee County BOE**  
**Wacoochee Jr. High School (Now Elementary)**  
**125 Lee Road 254**  
**Salem, Alabama 36874**

**REINSPECTION DATE:** 11/15/18

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL0518257655

**SIGNATURE:** Stan Eller


**COMMENTS AND INSTRUCTIONS:**

All changes in material are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- Any and all renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**




**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Wacoochee Jr. High School										School # 070									
Building Name - Wacoochee School										Building # 01									
Address: 125 Lee Road 254 Salem, Alabama 36874										Inspector's Name – Stan Eller									
										Signature - 									
Now: Wacoochee Elementary										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl Floor Tile (Classrooms) med. brown -12,500 sf		12" Vinyl Floor Tile (Kitchen Storage) white -170sf		1-Firedoor (Vault Room)		4- Firedoors (Lunchroom)		Plaster Skim Coat (Kitchen Washroom)		Sheetrock (Kitchen Area)		2- Firedoors (Hall Near Lunch room)					
			No.	30-01	32-06	51-01	51-02	33-06	22-06	51-03										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X	X	X	X	X	X	X	X	X	X				
	Assumed ACBM						X	X	X	X	X	X	X	X	X	X				
	Sampled/Tested		X		X							X		X						
	Non ACBM											X		X						
	ACBM		X		X							X		X						
	Nonfriable		X		X		X	X	X	X	X	X	X	X	X	X				
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N		N		Y		Y		N					
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
Public																				
Assessment Category			5	5	5	5														

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 11-12-15										Date Of Reinspection – 11-15-18									
LEA Name - Lee County Board of Education										LEA # 041									
School Name – Wacoochee Jr. High School										School # 070									
Building Name - Wacoochee Gymnasium										Building # 02									
Address: 125 Lee Road 254 Salem, Alabama 36874										Inspector's Name – Stan Eller									
										Signature - 									
Now: Wacoochee Elementary										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Vinyl Floor Tile (Coach's offices) white -700 sf		Vinyl Floor Tile (Storage) white - 30sf		2- Modine Gas Ceiling Heaters													
			No.	30-01	30-02	52-01														
Check one	TSI				X															
	Surfacing																			
	Miscellaneous	X		X																
	Assumed ACBM				X	X														
	Sampled/Tested	X		X																
	Non ACBM																			
	ACBM	X		X																
	Nonfriable	X		X		X	X													
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			Y	Y	N															
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
Public																				
Assessment Category			5	5	All Removed.		Not Listed Originally.													

70 SF remains @ coach's offices 12" VFT gray with white and black streaks. **All Removed.**

**W.S. ELLER CO., LLC/ DBA RAINCROW  
ENVIRONMENTAL  
752 MYRICK RD.  
DEATSVILLE, AL 36022  
(334) 315-2892**

# Invoice

DATE	INVOICE #
12/17/2018	2160

BILL TO	
Lee County Schools	
2410 Society Hill	
Opelika, AL 36804	
Attn: Accounts Payable	

DUE DATE	P.O. NUMBER
1/16/2019	

DESCRIPTION	AMOUNT
AMOUNT DUE ON ASBESTOS 3-YEAR INSPECTION & REPORT.	2,000.00

Thank you for your business!

**Total**

2,000.00

**W.S. ELLER CO., LLC/ DBA RAINCROW  
ENVIRONMENTAL  
752 MYRICK RD.  
DEATSVILLE, AL 36022  
(334) 315-2892**

# Invoice

DATE	INVOICE #
12/17/2018	2160

BILL TO	
Lee County Schools	
2410 Society Hill	
Opelika, AL 36804	
Attn: Accounts Payable	

DUE DATE	P.O. NUMBER
1/16/2019	

DESCRIPTION	AMOUNT
AMOUNT DUE ON ASBESTOS 3-YEAR INSPECTION & REPORT.	2,000.00

Thank you for your business!

Total

2,000.00

W.S. ELLER CO., LLC/ DBA RAINCROW  
ENVIRONMENTAL  
752 MYRICK RD.  
DEATSVILLE, AL 36022  
(334) 315-2892

# Invoice

DATE	INVOICE #
12/17/2018	2160

BILL TO	
Lee County Schools	
2410 Society Hill	
Opelika, AL 36804	
Attn: Accounts Payable	

DUE DATE	P.O. NUMBER
1/16/2019	

DESCRIPTION	AMOUNT
AMOUNT DUE ON ASBESTOS 3-YEAR INSPECTION & REPORT.	2,000.00

Thank you for your business!

<b>Total</b>	2,000.00
--------------	----------